

TO BE FILED BY THE INSPECTING OFFICER (ASST. ENGINEER)

- 1 Name of the Officer : JOHNSY T J
- 2 Name of the School : ST.Johns Public school,Parappukkara
- 3 Location with name of Education District/ Sub. District : Parappukkara,Irinjalakuda
- 4 Classification of Building as specified in column 4 of the application for fitness certificate and measurements specified in overleaf
- 5 Period for which the certificate is issued : 2019-20
- 6 Nature of defects , if any :
- a) Foundation and basement : Nil
- b) Superstructure : Nil
- c) Doors and Windows : Nil
- d) Wood work wrought and put up : Nil
- e) Roof : Nil
- f) Flooring : Nil
- g) Miscellaneous (Cracks, etc.) : Nil
- 7 Any major defects noticed which will render the building unsafe in any manner : No
- 8 Whether maintenance works have been done properly : Yes
- 9 Whether the structure is sound or not : Yes

Note : 1 The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.
2 Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Certified that the building was inspected by me on 30/05/19 and found to be fit for the period 2019-20 for the reasons stated above.

Place : Nandikkara

Date : 31/05/2019



Signature

Designation

[Handwritten Signature]
**ASSISTANT ENGINEER
L.S.G.D. Section
Parappukkara
Grama Panchayat**

Measurements

RCC building


GF 8 class rooms +WC 3+20 urinal

FF 8 class rooms +WC 4+15 urinal

SF 4 class rooms +WC 2+14 urinal+meeting hall



ASSISTANT ENGINEER
L.S.G.D. Section
Parappukkara
Grama Panchayat



ASSISTANT ENGINEER
L.S.G.D. Section
Parappukkara
Grama Panchayat

